



**STATEMENTS:**

**Mark Kass, Managing Director: Trading Enterprises – Honda**

**Dubai, UAE, Monday, February 01, 2010:**

“Trading Enterprises has received notification from its principals Honda Middle East that the GCC specification Honda Jazz and Honda City models are not subject to the safety recall. Regions which appear to have been affected are North America, Latin America, Europe, Africa and Asia. The safety recall relates to right-hand drive cars having power windows without the auto-close function. Cars sold in the GCC region are left-hand drive having power windows but with auto-close function.”

**Dubai, UAE, Wednesday, February 10, 2010:**

“Trading Enterprises has received notification from its principals Honda Middle East that the recall relating to an abnormal deployment of the driver-side airbag on the 2001 and 2002 model-year Accord, Civic, Odyssey and CR-V does not affect customers in the UAE.

“The recall relates to a dual-igniter type inflator which is not found in models in the UAE. Cars sold in the UAE use a single-igniter type inflator.”

Concerned owners are advised to contact [sunil.oommen@alfuttaim.ae](mailto:sunil.oommen@alfuttaim.ae) for further information.



# المشروعات التجارية

بيان:

مارك كاس، المدير الإداري، المشروعات التجارية- هوندا

دبي، الإمارات العربية المتحدة، الإثنين 1 فبراير 2010

"تلقت المشروعات التجارية إشعاراً من المسؤولين الرئيسيين في "هوندا الشرق الأوسط" يفيد أن طرازات هوندا جاز و هوندا سيتي حسب مواصفات دول مجلس التعاون الخليجي، لا تخضع لاستدعاء السلامة. وتضم المناطق المشمولة بالاستدعاء أمريكا الشمالية، أمريكا اللاتينية، أوروبا، أفريقيا وكذلك آسيا. ويتعلق استدعاء السلامة بالنوافذ العاملة بالكهرباء مع المقود في الجهة اليمنى دون وظيفة الإغلاق الآلي، فيما يوجد في سوق دول مجلس التعاون الخليجي سيارات بمقود على الجهة اليسرى، وكذلك نوافذ عاملة بالكهرباء مع وظيفة الإغلاق الآلي".

دبي، الإمارات العربية المتحدة، الأربعاء 31 فبراير 2010

"تلقت المشروعات التجارية إشعاراً من المسؤولين في هوندا الشرق الأوسط، يفيد أن الاستدعاء الخاص بالإنفتاح غير العادي، لوسادة الهواء الجانبية للسائق في سيارات، أكورد، وسيفيك، وأوديسي، وكذلك سي آر- في"، لطرازات العامين 2001 و 2002، لا تؤثر على العملاء في دولة الإمارات العربية المتحدة".

"وتتعلق قضية الاستدعاء بخرطوم إدخال الهواء مزدوج الإشعال، والذي لا يوجد في طرازات دولة الإمارات. وتتميز السيارات التي تم بيعها في الإمارات، بأنها مجهزة بخرطوم إدخال هواء أحادي الإشعال".

لذا ننصح مُلاك السيارات المهتمين بالاتصال على البريد الإلكتروني [sunil.oommen@alfuttaim.ae](mailto:sunil.oommen@alfuttaim.ae) للمزيد من المعلومات.